

THUTZHUAL SUPPORT NO14

PHENIX WEEKLY PLANNING



April 24, 2014 Don Lynch



This Week

TECHZHUAL SUPPORT 2014

- Run 14 Continues
- No Access this week
- Next access planned for next week 4/30
 - DC West wire repair? planning needed
 - MPC-Ex FEM replacement
 - Other Work
- Plan for 2014 Shutdown
- Tech Support for Run 14 as required
- Support for sPHENIX efforts as required






Next Week

- Run 14 Continues
- No access next week, next access 4/30:
 - MPC-Ex tweaking (access to FEMs required)
 - Other requests?
- Plan for 2014 Shutdown
- Tech Support for Run 14 as required
- Support for sPHENIX efforts as required

sPHENIX "Outie" Concept




This is the design we will continue to pursue until if and when a final decision directs us to the "innie" option




FECHZHUAL SUPPORT NO14


HCal Central Pedestal







sPHENIX Major Subsystem Envelope Drawing, rev E



April 24, 2014

sPHENIX Mechanical Design



sPHENIX Engineering:


Major Subsystems/Subtopics:

•	Magnet (BABAR) (Magnet Div) Hadronic Calorimeter (HCAL) (PHENIX) EM Calorimeter EMCal (PHENIX) VTX (RIKEN) DIRC (?)	start 2/1, start 2/1, start 2/1, start 2/1, start	/14 /14 /14 ?	- 12/ - 12/ - 12/ - 12/	31/20 31/20 31/20 31/20	020 020 020 020
	VTX additional layers (RIKEN)	start	.	- 12/	31/20)20
•	Carriage Support structure (PHENIX)	start 2/1	/14	- 12/	31/2	020
•	Readout Electronics (PHENIX)	start 2/1	/14	- 12/	31/2	020
•	Infrastructure (PHENIX ++)					
	 Electrical Power Services (PHENIX 	()start	?	- 12/	31/17	7
	 Instrumentation Support 	start	? .	- 12/	31/20	020
	(Signal trays & Racks) (PHENIX)					
	· Cryo Services (CAD)	start 2/1	/14	- 8/1	/18	
	 Cooling water (CAD) 	start	?	- 12/	31/20)17
	 Safety Systems (PHENIX) 	start	? .	- 12/	31/20	20
	 Work Platforms and Access/Egress 				31/20	
	Structures (CAD)					
	· HVAC (CAD)	start	2.	- 12/	31/20)17
	 PHENIX Decommissioning 	start			0/20	
	(CAD, PHENIX)					
•	System Integration (PHENIX)	start 2/1	/14	- 12/	31/2	020
	Testing (PHENIX)	start 2/1,				
	Installation (PHENIX, CAD)	start 2/1,				
	Commissioning (PHENIX)	start 2/1,				
	Total and the second se	J. W. 1 2/ 1/	- '	/	0 - , -	



Magnet (BABAR) (Magnet Div)


•	Acquire rights	Done		
•	Evaluate Transport 5/1/14			
•	Design Transport fixtures			
•	Fabricate Transport Fixtures	5/1/14		
•	Evaluate BNL test facility requiremen	nts 6/1/1		
•	Prepare test facility	8/1/14		
•	Install Transport fixtures			
•	Transport to BNL	9/1/14		
•	Install in test facility	10/1/14		
•	Design tests/test equipment	10/1/14		
•	Fabricate/procure test equipment	1/1/15		
•	Run tests	6/1/15		
•	Design Magnet modifications	12/1/14		
•	Fabricate magnet modifications	6/1/15		
•	Install magnet modifications	8/1/15		
•	Evaluate final installation	9/1/15		
•	Design installation support equipment			
•	Fabricate/procure support equipment			
•	Transport to IR			
•	Install			
•	Test			
•	Commission			







Magnet (BABAR) (Magnet Div)


•	Acquire rights	Done		
•	Evaluate Transport	5/1/14		
•	Design Transport fixtures			
•	Fabricate Transport Fixtures	5/1/14		
•	Evaluate BNL test facility requiremen	nts 6/1/14		
•	Prepare test facility	8/1/14		
•	Install Transport fixtures			
•	Transport to BNL	9/1/14		
•	Install in test facility	10/1/14		
•	Design tests/test equipment	10/1/14		
•	Fabricate/procure test equipment	1/1/15		
•	Run tests	6/1/15		
•	Design Magnet modifications	12/1/14		
•	Fabricate magnet modifications	6/1/15		
•	Install magnet modifications	8/1/15		
•	Evaluate final installation	9/1/15		
•	Design installation support equipment	12/31/201	6	
•	Fabricate/procure support equipment	7/1/2018		
•	Transport to IR	7/1/2018		
•	Install	10/31/201	9	
•	Test	11/31/2019	9	
•	Commission	12/31/201	9	




FECHZHUAL SUPPORT NO14










4/24/2014


11

THUHZHUAL SUPPORT NO14



BABAR Magnet Shipping Fixtures:

3 of each required to immobilize the cold mass heat shield








THUTZHUAL SUPPORT

2ft high x 1 ft wide clearance needed for e-ring components

ePHENIX







Plan View 4/24/2014

13



2014 planned Technical Support & 2014 Shutdown

	•	
T	Support for run 14	2/3-6/30/2014
Ė	Procure & Fabricate parts for MPC-Ex North and South	1/1/2014-6/30/2014
	Assemble & test MPC-Ex South, ready for installation	3/1-7/1/2014
$\boldsymbol{\mathcal{C}}$	End of Run Party	7/11/14?
ŭ	Assemble & test MPC-Ex North, ready for installation	7/1-9/25/2014
	Start of Shutdown Tasks (purge flammable gas, disassemble and	
N	stow shield wall, remove collars, move EC to AH, Move	
I	MMS south, etc.)	7/14 - 7/25/2014
	Remove FVTX/VTX East to PHYSICS?, repair and reinstall	7/14 - 9/15/2014
~	Remove MMS east vertical lampshade	7/28-7/30/2014
- MOTZHOK-	Troubleshoot intermittent water leak in MMS	7/30- 8/8/2014
	Other Maint. In MMS	TBD
	Reinstall MMS east vertical lampshade	TBD
	Summer Sunday prep AH, tours and restore AH	7/30-8/15/2014
5	Install scaffolding in Sta 1 South	7/28/2014
U	Remove MPC-Ex prototype, Install new MPC-Ex South	7/28-8/22/2014
SUPPORT	Maint. & Repairs for MPC South, BBC South, RPC1 South, MuTr sta 1	
	South, as necessary	7/28-8/22/2014
P	Remove scaffolding from sta 1 south, Move CM South	8/25/2014
0	Install scaffolding in Sta 1 North	8/26-8/29/2014
Ď	Prep MPC-Ex North installation area	9/1-9/26/2014
<u>\$</u>	Install new MPC-Ex North	9/29-10/17/2014
	Remove Sta 1 North scaffolds, Move CM North	10/20-10/24/2014
	Other detector support	TBD
2	Infrastructure Maintenance and Improvement	TBD
2 0 1 4	Decommissioning of obsolete PHENIX detector equipment	TBD
U	sPHENIX Support	on-going
1	End of Shutdown Tasks (Move MS north, roll in EC , install collars,	3 3
Ā	remove 10 ton cart, plates and manlifts, build shield wall, etc.)	10/27-11/26/2014
7	Pink/White/Blue Sheets	1/17/2014
	End of Shutdown Party	5 555
	Start Flammable gas flow	5555
	Close shield wall, install radiation interlocks and prepare for run 14	12/31/2014
	Start run 15	1/2/2015



Safety and Security

From Ray Karol:

- 1. Reminder: do not prop open doors especially Access Controls doors without permission of RSC Chair, A. Etkin, R, Karol or Ed Lessard.
- 2. Reminder: Do not move rad postings or ropes, only HP can do this.
- 3. Based on a requirement change in the National Fire Protection Association's Standard for Electrical Safety in the Workplace NFPA 70E, the Laboratory Electrical Safety Committee (LESC) has recently rendered a decision that ear protection (specifically, ear canal inserts) is required when performing electrical work at BNL on equipment with a Hazard/Risk Categorization of 0 or greater.

Any ear canal inserts that do not have bands or cords available through the EPRO system will meet the requirement of the Standard.


Safety and Health Services Division will be working with the LESC and the Training Office to make the appropriate changes to the Subject Area and impacted training. Additional guidance is expected in the near future.

Please ensure that from this point forward you wear ear canal inserts when operating circuit breakers or switches, or are performing electrical energized work on equipment identified as having a Hazard/Risk Category of 0 or greater.

Applies to all staff who have taken *Electrical Safety* 1 and *Electrical Circuit Breaker and Switch Operation Safety* training



PHENIX Safety and Security



Injury Status:

FY14 YTD: DART – 11, TRC – 21, First Aid – 26 FY13: DART – 16, TRC – 38, First Aid – 53 FY12: DART – 19, TRC – 36, First Aid – 69

FY13 Injury Listing: https://intranet.bnl.gov/esh/shsd/seg/Occlni/BNLInjuries.aspx

Recent Inju	ıries		
		None	



FECHZHUAL SUPPORT NO14

Recent Eve	Recent Events			
4/12/14	4/12/14 Non-Reportable Fire Rescue responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil on the responded to a reported spill of approximately 30 gallons of motor oil			
4/11/14	Non- Reportable	During scheduled water sampling by the RHIC ring storm water outfall, Environmental Sampling Team personnel discovered oil sheen on the water before and after the weir. Fire Rescue responded along with Environmental Protection Division (EPD) staff. Oil adsorbent pads and a boom were set in place downstream of the weir to mitigate further spread of the observed oil sheen. Investigation to identify the source of the spill is ongoing and involves the EPD and Collider-Accelerator Department (C-AD). It is estimated that the amount of oil released was less than 1 gallon. (Event Link)		
4/10/14	Non- Reportable	Due to the failure of a corroded metal bushing on the feed pump to a 150-gallan tank of sodium hypochlorite solution, approximately 100 gallons of the solution leaked into the secondary containment tray beneath the tank. Chemical treatment vendor staff isolated the leak and repaired the feed pump, after which the product was returned to the storage tank. There were no injuries associated with the incident and hazardous materials were not released to the environment. (Event Link)		



Where To Find PHENIX Engineering Info

Run 14 Continues!



NY Jets 2014 Season announced:

9/7 Raiders @ Jets

9/14 Jets @ Packers

9/22 Bears @ Jets (Monday night)

9/28 Lions @ Jets

10/5 Jets @ Chargers

10/12 Broncos @ Jets

10/16 Jets @ Patriots (Thursday night)

10/26 Bills @ Jets

11/2 Jets @ Chiefs

11/9 Steelers @ Jets

11/16 BYE

11/23 Jets @ Bills

12/1 Dolphins @ Jets (Monday night)

12/7 Jets @ Vikings

12/14 Jets @ Titans

12/21 Patriots @ Jets

12/28 Jets @ Dolphins

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm